

## INSIGHT® Classic Stud Retainer Assembly Repair

The following information is provided to help you replace the seat and back onsert stud retainer assembly.


### Tools Needed

- Special 11SP Vice-Grip® clamp. American Seating (AS) Part Number (PN) 155769000.

### Assembly Components




Remove all broken or malfunctioning stud retainer assembly components.



Stud retainer assembly includes upper spring clip (AS-PN 150-792-000) and lower clip retainer (150-793-000).

### Assembly Replacement



Hold in place the lower clip retainer into the bottom hole with clamp bottom (1 x 1" square tube section).



Position upper spring clip into top hole.



Close clamp to secure upper and lower components together. Should hear an audible click when they are connected.



Finished assembly may rotate in the hole, but it is now ready to reattach onserts.